

FB
22/11/14

KERALA STATE ELECTRICITY BOARD

(Incorporated under the Indian Companies Act, 1956)
Registered Office: Vidyuthi Bhavanam, Pattom
Thiruvananthapuram-695 004

DY. CE	Transmission Circle Thiruvananthapuram 6715	
EE	25 OCT 2014	FO
SS	INWARD	Section

ABSTRACT

Revising the staff pattern of the Line Maintenance Sections under Transmission wing-sanction accorded- orders issued

Corporate Office (SBU-T/SO)

B.O.(FTD)No.2753/2014(D(T&SO)/T2/reorganisation/2014)

Thiruvananthapuram Dated: 24.10.2014

- Read: 1. B.O.(FB)No.1476/2009(TPC3/51/2006) dtd 04.06.2009
2. Letter No.CE(TS)/EE2/AEEIX/TVM-General/626 dtd 26.09.2014 of the Chief Engineer(Trans.South)
3. Order No.EB4(a)/promotion/worker to LMII/2014-15 dtd 20.09.2014
4. FTD Note No. D(T&SO)/T2/reorganisation/2014) dtd 10.10.2014 of the Director (Trans.& System Operation)

ORDER

The Line Maintenance Sections under transmission wing are carrying out the rectification of the breakdown and periodical maintenance of all EHT lines for which skilled and experienced workmen are required. The Chief Engineer (Trans.South) as per the letter read above reported that experienced electricity workers under Line Maintenance Sections on promotion as Lineman are posted to electrical sections under distribution wing. As per the present staff pattern there is no sanctioned place of lineman under LM sections. But as the services of skilled and experienced field staff with sufficient exposure in line maintenance works are essential for attending to break down as well as preventive maintenance works, the Chief Engineer(Trans.South) suggested that the present staff pattern of LM section may be revised as follows so that the services of experienced staff can be utilised:

Designation	Present staff pattern (as per order read (1) above)	revised staff pattern
Asst.Engineer (Ele)	1	1
SubEngineer (Ele)	1	1
Overseer(Ele)	2	1
Lineman	0	3
Ele.workers	5	3
Total	9	9

It is reported that there is no additional financial commitment to Board by way of the revising the staff pattern of LM sections as above.

Having considered the above, sanction is hereby accorded :

1. to revise the staff pattern of Line Maintenance sections under transmission wing as follows:

Asst. Engineer(Ele)	1 no
Sub Engineer(Ele)	1 no
Overseer	1 no.
Lineman	3 nos. ✓
Electricity Worker	3 nos.

2. to retain the Electricity workers in Line Maintenance Sections promoted as Lineman vide promotion order read (3) above in the present office itself after effecting promotion until further orders.

The Chief Engineer(HRM) shall take further necessary action accordingly.

By Order of the Full Time Directors
Sd/-

M.SHAHUL HAMEED
SECRETARY(Administration)

To

The Chief Engineer(HRM)

The Chief Engineer(Trans. South)/ Chief Engineer(Trans.North)

Copy to:

The Financial Adviser/The Chief Internal Auditor ✓

The Deputy Chief Engineer, Transmission Circle, Thiruvananthapuram/
Kottarakkara/Alappuzha/Poovanthuruthu/Thodupuzha/Kalamassery/

Thrissur/Palakkad/Malappuram/Kozhikode/Kannur

The Executive Engineer, Transmission Division, Pathanamthitta

The Deputy Chief Engineer(IT)

The RCAO/The RAO


The TA to Chairman & Managing Director/ Director (Transmission &
System Operation)/Director (Distribution & Safety)/Director (Gen.Civil)/
Director(SCM & Generation-E)/ Director(Renewable Energy & Planning).

The PA to Director(Finance)/Secretary (Administration).

The Fair Copy Superintendent.

Library/Stock File.

Forwarded / By Order



Assistant Executive Engineer